

Message

---

**From:** Wayne Miller [Miller.Wayne@azdeq.gov]  
**Sent:** 5/4/2018 5:35:00 PM  
**To:** Davis, Eva [Davis.Eva@epa.gov]; d'Almeida, Carolyn K. [dAlmeida.Carolyn@epa.gov]; Dan Pope [DPope@css-inc.com]  
**Subject:** 2018-5-4 - wafb - sent request for LNAPL recovery info - ST012 -uxo site visit-

Forwarded info request.

---

**From:** Davis, Eva [mailto:Davis.Eva@epa.gov]  
**Sent:** Friday, May 04, 2018 10:27 AM  
**To:** d'Almeida, Carolyn K. <dAlmeida.Carolyn@epa.gov>; Dan Pope <DPope@css-inc.com>; Wayne Miller <Miller.Wayne@azdeq.gov>  
**Subject:** 2018-5-4 - wafb - request for LNAPL recovery - ST012 -uxo site visit-edavis epa

It would be interesting to know if they are recovering LNAPL from the wells they are pumping. Maybe Steve could ask them next time he is out there?

---

**From:** d'Almeida, Carolyn K.  
**Sent:** Thursday, May 03, 2018 3:35 PM  
**To:** Davis, Eva <Davis.Eva@epa.gov>; Dan Pope <DPope@css-inc.com>  
**Subject:** FW: 2018-5-3 - wafb -FYI - uxo 5-2-2018 PFAS & ST012 EBR site visits - sw uxo

FYI – memo from Steve: mixing tanks and piping for EBR are going in.

Carolyn d'Almeida  
Remedial Project Manager  
Federal Facilities Branch (SFD 8-1)  
US EPA Region 9  
(415) 972-3150

*"Because a waste is a terrible thing to mind..."*

---

**From:** Wayne Miller [mailto:Miller.Wayne@azdeq.gov]  
**Sent:** Thursday, May 3, 2018 1:13 PM  
**To:** d'Almeida, Carolyn K. <dAlmeida.Carolyn@epa.gov>; JERRARD, CATHERINE V CIV USAF HAF AFCEC/CIBW <catherine.jerrard@us.af.mil>  
**Subject:** 2018-5-3 - wafb -FYI - uxo 5-2-2018 PFAS & ST012 EBR site visits - sw uxo

FYI -

---

**From:** Steve Willis [mailto:steve@uxopro.com]  
**Sent:** Thursday, May 03, 2018 9:35 AM  
**To:** Wayne Miller <Miller.Wayne@azdeq.gov>  
**Subject:** 2018-5-3 - wafb - uxo 5-2-2018 PFAS & ST012 EBR site visits - sw uxo

Wayne,

Attached is a summary of my site visit to the Former Williams AFB on Wednesday, May 2. Nothing too exciting. They had just completed well WILPMW002 and were going to start construction. WILPMW008 was halted for rig maintenance. I observed drilling for a while after repairs were made, then went to ST012 to check on the status there.

Steve

Steven A. Willis  
UXO Pro, Inc.  
[steve@uxopro.com](mailto:steve@uxopro.com)  
480-316-3373